



BOX 1000, JACKSON, MI 49204-1000
517-764-6060 • FAX 517-764-5607


November 25, 1996

TO WHOM IT MAY CONCERN:

Unisorb Inertia Block Material which is specified as IB-500-B1 and IB-500-S2 is not considered hazardous under normal conditions of use, and by definition, as provided in OSHA'S HAZARD COMMUNICATION STANDARD; CFR TITLE 29,1910.1200(c) (i-iii).

In addition, Unisorb Inertia Block Material does not produce any unusual combustion gases other than those that would be normal to wool, synthetic organic fibers, or other organic materials.

Signed By:


Richard A. Haase
Chief Engineer

RAH:ab